

Pelegrin SIA.

Traleru iela 30, LV-1030, Latvia info@tarragonaircraft.com

Tel: +371 28 623 746

SERVICE BULLETIN No. 19-05-25-4

Date released: 19 May 2025 Date effective: 19 May 2025

MANDITORY

SUBJECT: Release of Updated Pilot Operating Handbook (POH) – Issue 2, Rev. 0

AFFECTED AIRCRAFT SERIAL

NUMBER:

From TXXXXXX035 up to TXXXXXX038

BACKGROUND: The updated Pilot Operating Handbook – Issue 2, Rev. 0 has been

developed to provide revised operational guidance, performance data, and procedural information for released models. It includes

critical updates to aircraft weight and balance calculation, emergency procedures, and operating limitations. It provides essential information on equipment, operating procedures,

performance, and recommended care. Pilots are encouraged to read it thoroughly and always keep it readily available for reference.

PURPOSE: This bulletin is issued to announce the release of the updated Pilot

Operating Handbook – Issue 2, Rev. 0 for all recently released

models. This new handbook replaces all previous versions, which are

no longer valid for use.